

Type	Size	← SOFT HARDNESS HARD →	
U	30x960	[Blue bar representing hardness level]	
N	30x960	[Blue bar representing hardness level]	
H	30x960	[Blue bar representing hardness level]	
P	40x1060	[Blue bar representing hardness level]	
N	40x1060	[Blue bar representing hardness level]	
E	50x1030	[Blue bar representing hardness level]	
U	50x1030	[Blue bar representing hardness level]	
Q	50x1030	[Blue bar representing hardness level]	
N	50x1030	[Blue bar representing hardness level]	
H	50x1030	[Blue bar representing hardness level]	
HH	50x1030	[Blue bar representing hardness level]	
HD	50x1030	[Blue bar representing hardness level]	

